

**FOLKESTONE HARBOUR
COMPANY LIMITED**

NOTICE TO MARINERS
No 11 of 2017

DEBRIS IN OUTER HARBOUR

Outer Harbour Mooring Area

It has been reported to the Harbour Manager that a certain amount of debris has been observed in the outer harbour. This debris is lying on the sea bed and does not significantly affect the depths encountered by harbour users. However, it is recommended that harbour users check their berth area at low tide. Any debris that harbour users consider requires the attention of the Harbour Manager should be reported immediately.

South Quay

Reports of substantial debris alongside the South Quay are being investigated and so until further notice the whole area adjoining the South Quay must not be used over low water. It is noted that the debris alongside the South Quay significantly reduces the depths available. As such the South Quay, can no longer be considered a NAABSA* berth.

Further investigations regarding all debris is being undertaken by FHC.

*NAABSA = Not Always Afloat But Safely Aground,

Date: 31st August 2017

**Folkestone Harbour Company Limited
Port Office
Folkestone Harbour
Kent CT20 1QH**

**Mrs Lorraine Hughes
Harbour/Port Manager**

**Expiry Date: T.B.A.
To Receive Future Notices to Mariners please see
Our website: www.folkestoneharbour.com**