

FOLKESTONE HARBOUR COMPANY LIMITED

NOTICE TO MARINERS No 8 of 2017

Timber Piles Exposed in NE Corner of Harbour

During dredging works timber piles suspected to be the foundations of a redundant jetty have been found within the Outer Harbour.

The position of the piles are $51^{\circ} 4' 49.8''N$ $1^{\circ} 11' 22.7''E$ (see picture below) and protrude approximately 1 metre above current bed level.



It is recommended that a 20 metre exclusion zone is operated around this navigation risk.

All port users should be aware and must observe this exclusion area. This notice to mariners will be cancelled when the item is removed.

Date: 6th April 2017

Folkestone Harbour Company Limited
Port Office
Folkestone Harbour
Kent CT20 1QH

Mrs Lorraine Hughes
Harbour/Port Manager

Expiry Date: T.B.A.
To Receive Future Notices to Mariners please see
Our website: www.folkestoneharbour.com